

Technical Service Bulletin Number	Revision Level	Date	Group Number
TSB130159			



Technical Service Bulletin

Subject

Fault Code 3167 or 1691 Caused by a Missing Poppet in the EcoFit™ Aftertreatment Fuel Injector

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document informs the field of a missing poppet in the EcoFit™ aftertreatment fuel injector causing Fault Code 3167 or 1691.

This issue is isolated to the new EcoFit™ aftertreatment fuel injector design. The new EcoFit™ aftertreatment fuel injector is susceptible to the inner poppet falling out due to a worn retaining spring retainer. This situation can increase the probability of fouling that can cause a high restriction of the injection of fuel into the aftertreatment system.

See Table 1 to reference the affected part numbers:

Table 1		
Engine Family	EcoFit™ Aftertreatment Fuel Injector Part Number	EcoFit™ Aftertreatment Fuel Injector Service Kit Part Number
ISX CM871 ISM CM876	5300987	4309454NX
ISX 12		

CM2250		
ISX 15		
CM2250		
QSX11.9		
CM2250		
QSX15	5294110	4309349NX
CM2250		
ISX12		
CM2350		
ISX15		
CM2350		


- ε The engine control module (ECM) illuminates the amber CHECK ENGINE lamp and/or the malfunction indicator lamp (MIL).
- ε Fuel injection into the aftertreatment system is **not** sufficient to perform active regeneration of the aftertreatment diesel particulate filter.

Malfunctioned EcoFit™ aftertreatment fuel injectors will have a hole in the center of the injection point. A normal EcoFit™ aftertreatment fuel injector will have a visible plunger (poppet) at the center of the injection point.



Missing Poppet - EcoFit™ Aftertreatment Fuel Injector

©Cummins Inc



11a00097

Poppet - EcoFit™ Aftertreatment Fuel Injector

If the EcoFit™ aftertreatment fuel injector is missing the lower poppet, replace the aftertreatment fuel injector.

Document History

Date	Details
2013-11-4	Module Created
2014-5-8	typo correction

Last Modified: 09-May-2014

Copyright © 2000-2010 Cummins Inc. All rights reserved.